Work Order ID 113215 *113215* Page 1 February-12-14 8:59:42 AM Item ID: D3589-1 Accept *N900040100* Setup Start **Revision ID:** Item Name: Arm *N.S.2* Start Date: 2/10/14 Start Qty: 6.00 *6* **Cust Item ID:** Required Date: 2/10/14 Reg'd Qty: 6.00 *6* **Customer:** Reference: Run Start Date: 1402.14 Tooling: Date: Approvals: **Process Plan:** Stop QC: Date: SPC (Y/N): Date: *NR2* Sequence ID/ **Operation** Set Up/ Tool ID Tool # Plan Reject Reject Accept Insp. Work Center ID **Description** Number Stamp **Run Hours** Code Qty Qty Draw Nbr **Revision Nbr** D3589 C 100 0.00 *100* Small Fab 0.00 Memo Small Fab 1- cut D3589-1 as per dwg D3589 2- chamfer both ends as per dwg D3589 3- deburr DAS 110 QC5- Inspect part completeness to step on W/O 0.00 27 *110* Memo Quality Control DAS Identify as per dwg & Stock Location: 0.00 120 32 *120* LAOUZ

0.00

Memo

Packaging

Packaging

DQA:			Date:													
QA Closed: Date:						WORK ORDER NON-CONFORMANCE / UPDATE Work Order update only Work Order update only										
QA Closed.			Date.			work Order update only										
Work Orde	er:					DISPOSITION		AGAINST DEPARTMENT/PROCESS								
						Rework			Skid-tube Cro	sstube		Engineering				
Part N	lo.				:	Scrap		1	Machining Sm	all Fab	Pro	d. Eng. Coor.	Quality			
						Use-as-is		Thern	noforming Fir	nishing	Rec/Stor	Other				
NCR N	No	11.1				Suspected Unapproved			Large Fab Com	nposite 🔃	į	Supplier				
					<u> </u>	:			Á -4:		c: o					
Root		Date Step Qty		Desci	ription of work order update	1	nitial	Action		Sign &	Vanifiaatian	001				
Cause	\dashv	Date	Step	Qty		or non-conformance	Cn	ief Eng	Description		Date	Verification	QC Inspector			
Design Doc/Data	\dashv									:						
Equip/Tooling	\dashv															
Handling/Pre	_															
Material																
Operator																
Offset/Setup							ļ									
Process																
Supplier																
Training							ļ									
Transport		!														
Unapproved																
							FA	ULT CA	regory							
Landi	ng Ge	ar				General		_				_	_			
	B₁	ending				Bend	Folio/Program				Outside Dim	ensions	Pressure/Forced			
	Centre Not Concentric			ntric		BOM/Route		Grain			Over/Under	tolerance	Set-up			
	Cracks				_	Broken/Damage/Defect		Hardwa	ire		Part Incorrect		Temperature/Cure			
	Crimp/Kink/Ripple/Wave				_	Burrs	_	1	ion Incomplete/Unqualifi	<u> </u>	Part Lost/Missing		Weld			
	Cuffs				ļ	Contamination	_	4	ions Incomplete/Unclear	·	Part Moved		Wrong Stock Pulled			
		rushing			<u> </u>	Countersink		4	ned/off center		Positioned V	_	,			
	Heat Treat					Cut Too Short	<u> </u>	Mislabe			Power Loss/	Surge	Other			
	${f}$	•	n Strip in	Tube	\vdash	Drawing	<u></u>	Misread				· · · · · · · · · · · · · · · · · · ·				
	lacksquare	1arks/Ch			<u> </u>	Drill Holes	<u> </u>	Off-set				<u>-</u>				
			equence		<u> </u>	Finish	\vdash	4	Calibration							
	Wave/Twist in Tube					Fit/Function	1_	Out of S	Sequence							

Work Orde February-12-14				*119	3215	*				-			Pag	;e 2
	D3589-1 Arm 2/10/14	Start Qty: 6.00	*6*	Accept	*N9(100)*	Setup	Start Stop		S1* S2*	
Required Date: Reference:	2/10/14	Req'd Qty: 6.00	*6*		Custo	mer:								
Approvals:	Process Pla	an:	Date:	Tooling: SPC (Y/N):		Dan Dan				Run	Start Stop		R1*	
Sequence ID/ Work Center II 130 *1.20* QC Quality Control		Operation Description QC21- Final Inspection - Memo	Work Order Release	Set Up/ Run Hours 0.00	Tool	ID	Tool #	Plan Code	Accept Qty		, I	Reject Number	Insp. Stamp	

DQA:			Date:												
					,	WORK ORDER NON-CONFORMANCE / UPDATE									
QA Closed:			Date:						·	Wo	ork Order up	date only			
Work Order:						DISPOSITION									
WOIK OIG	-					Rework		Skid-tube	Crosstube	1	Water Jet		Engineering		
Part N	No.					Scrap			Machining	Small Fab	Pro	d. Eng. Coor.		Quality	
	•					Use-as-is]	Therr	noforming	Finishing				Other	
NCR N	۱o.					Suspected Unapproved			Large Fab	Composite	}	Supplier	_]		
Root		·			Desc	ription of work order update	П	nitial	Actio	n	Sign &				
Cause		Date	Date Step Qty			or non-conformance	Ch	ief Eng	Description		Date	Verification	1	QC Inspector	
Design												•			
Doc/Data							ļ								
Equip/Tooling															
Handling/Pre															
Material															
Operator						•	1								
Offset/Setup											ļ				
Process												:			
Supplier			Ì												
Training									'						
Transport			ļ												
Unapproved			į		-										
							FA	ULT CA	TEGORY						
Landi	ng (1			_	General	_	1 .			7	-	-		
	Ш	Bending				Bend	L	1	Program	_	Outside Dim	<u> </u>		Pressure/Forced	
	<u> </u>	Centre Not Concentric			<u> </u>	BOM/Route	\vdash	Grain			Over/Under	- H		Set-up	
	_	Cracks				Broken/Damage/Defect	<u>_</u>	Hardwa		<u> </u>	Part Incorrect			Temperature/Cure	
	Crimp/Kink/Ripple/Wave				\perp	Burrs	<u> </u>	Inspection Incomplete/Unqualified			Part Lost/Missing			Weld	
	Cuffs				<u> </u>	Contamination	_	4	tions Incomplete/Un	nclear	Part Moved	Į		Wrong Stock Pulled	
		Crushing				Countersink	_	4	gned/off center	<u> </u>	Positioned V				
	Heat Treat					Cut Too Short	—	Mislab			Power Loss/Surge			Other	
	_	Inspectio	•	Tube		Drawing		Misrea							
	<u> </u>	Marks/Ch				Drill Holes	<u></u>	Off-set							
	ldash	Turning S	•			Finish		4	Calibration						
		Wave/Tw	vist in Tub	oe .		Fit/Function		Out of Sequence							

Picklist Print Page 1 February-12-14 8:59:45 AM Work Order ID: 113215 *113215* **Parent Item:** D3589-1 *D3589-1* Parent Item Name: Arm **Start Date: 2/10/14** Required Date: 2/10/14 Start Qty: 6.00 Required Qty: 6.00 **Comments:** IPP Rev:A 08-05-29 new issue DD verified by:EC IPP Rev:B 09-02-20 rev.b asper dwg DD verified by:EC Replacement Mfg/ Component Item ID/ Bin Primary Last Route Unit of Qty on Qty per Kit Total Qty Date Status **Item Name** Seq ID Item ID Purch Item Location Location Measure Hand **Qty Issued Issued** M304TR0.375W.065 Purchased No 100 f 27.4200 1.65 9.949749 ** *M304TR0 375W 065* FF 14-03-13 304 RD Tube .375 x .065W

 Location
 Loc Qty
 Loc Code

 MAT016
 27.42

 124768
 27.42

DQA:			Date:											
						WORK ORDER NON-CONFORMANCE / UPDATE								
QA Closed:			Date:							V	Vork Order u	odate only		
Work Orde	er:					DISPOSITION								
l vvoik orak						Rework		Skid-tube	Crosstube		Water Jet	Engineering		
Part N	No.					Scrap			Machining	Small Fab	Pro	d. Eng. Coor.	Quality	
	•					Use-as-is			noforming	Finishing		re/Packaging	Other	
NCR I	۷o.					Suspected Unapproved			Large Fab	Composite		Supplier		
												·-		
Root		Desc			Desc	ription of work order update		nitial	Actio	on	Sign &			
Cause		Date	Step	Qty		or non-conformance	Ch	ief Eng	Description		Date	Verification	QC Inspector	
Design														
Doc/Data	Ш													
Equip/Tooling	Ш													
Handling/Pre	Щ										Ì			
Material	Н													
Operator	Ш						1							
Offset/Setup	Ы						ŀ							
Process	Н													
Supplier	H													
Training	\vdash						İ							
Transport Unapproved	-						'				İ			
Опаррточец			<u>.i</u>		!	·	FΔ	III T CA	TEGORY		_1	<u> </u>		
Landi	ng G	iear				General	10	OLI CA	ILGONI					
		Bending				Bend] Folio/F	Program	Γ	Outside Dim	ensions [Pressure/Forced	
		Centre Not Concentric				BOM/Route		Grain		F	Over/Under	 	Set-up	
	Н	Cracks				Broken/Damage/Defect	Hardwa	are	<u> </u>	Part Incorre	-	Temperature/Cure		
	Crimp/Kink/Ripple/Wave					Burrs		4	ion Incomplete/Und	gualified	Part Lost/M		Weld	
	Cuffs					Contamination		4	ructions Incomplete/Unclear		Part Moved		Wrong Stock Pulled	
	Crushing					Countersink		4	gned/off center	<u> </u>	Positioned \	_	-	
	Heat Treat					Cut Too Short		Mislabe	=		Power Loss/	Surge [Other	
		Inspectio	n Strip in	Tube		Drawing		Misrea	d	_		-		
		Marks/Cl	natter			Drill Holes		Off-set						
		Turning S	Sequence			Finish		Out of	Calibration					
		Wave/Tw	vist in Tub	e		Fit/Function	Г	Out of	Sequence					



